

C.L. "BUTCH" OTTER – Governor RICHARD M. ARMSTRONG – Director DEBBY RANSOM, R.N., R.H.I.T - Chief BUREAU OF FACILITY STANDARDS 3232 Elder Street P.O. Box 83720 Boise, Idaho 83720-0036 PHONE: (208) 334-6626 FAX: (208) 364-1888 E-mail: fsb@idhw.state.id.us

April 13, 2007

Victoriana Andonegui Ireland, Administrator Spring Creek Manor IV, LLC 653 N Eagle Rd Eagle, ID 83616

License #: RC-780

Dear Ms. Ireland:

On February 21, 2007, a life safety code survey was conducted at Spring Creek Manor IV, LLC. As a result of that survey, deficient practices were found. The deficiencies were cited at the following level(s):

• Non-core issues, which are described on the Punch List, and for which you have submitted evidence of resolution.

This office is accepting your submitted evidence of resolution.

Should you have questions, please contact Taylor Barkley, Health Facility Surveyor, Facility Fire, Life Safety, and Construction Program, at (208) 334-6626.

Sincerely,

TAYLOR BARKLEY

Team Leader

Health Facility Surveyor

Facility Fire Safety & Construction Program

TB/sc

c:

Mark Grimes, Supervisor, Facility Fire Safety & Construction Program

C.L. *BUTCH* OTTER, Governor RICHARD M. ARMSTRONG – Director DEBBY RANSOM, R.N., R.H.I.T - Chief BUREAU OF FACILITY STANDARDS 3232 Elder Street P.O. Box 83720 Boise, Idaho 83720-0036 PHONE: (208) 334-6626 FAX: (208) 364-1888 E-mail: fsb@idhw.state.id.us

February 23, 2007

Victoriana Andonegui Ireland, Administrator Spring Creek Manor IV, LLC 653 N Eagle Rd Eagle, ID 83616

Dear Ms. Andonegui Ireland:

On February 21, 2007, a life safety code survey was conducted at Spring Creek Manor IV, LLC. The facility was found to be providing a safe environment for its residents.

The enclosed form, stating no core issue deficiencies were cited during the survey, is for your records only and need not be returned.

Please bear in mind that non-core issue deficiencies were identified on the punch list, a copy of which was reviewed and left with you during the exit conference. The completed punch list form and accompanying proof of resolution (e.g., receipts, pictures, policy updates, etc.) are to be submitted to this office by March 23, 2007.

Should you have any questions about our visit, please contact me at (208) 334-6626.

Sincerely.

MARK GRIMES

Supervisor

Facility Fire Safety & Construction Program

MG/slc

Enclosure

(X6) DATE

Bureau of Facility Standards

STATEMENT OF DEFICIENCIES (X3) DATE SURVEY (X1) PROVIDER/SUPPLIER/CLIA (X2) MULTIPLE CONSTRUCTION AND PLAN OF CORRECTION COMPLETED **IDENTIFICATION NUMBER:** 01 - ENTIRE BUILDING A. BUILDING B. WING 13R780 02/21/2007 STREET ADDRESS, CITY, STATE, ZIP CODE NAME OF PROVIDER OR SUPPLIER 653 N EAGLE RD SPRING CREEK MANOR IV, LLC **EAGLE, ID 83616** (X4) ID PREFIX SUMMARY STATEMENT OF DEFICIENCIES PROVIDER'S PLAN OF CORRECTION (X5) COMPLETE ID (EACH DEFICIENCY MUST BE PRECEDED BY FULL (EACH CORRECTIVE ACTION SHOULD BE PREFIX REGULATORY OR LSC IDENTIFYING INFORMATION) DATE CROSS-REFERENCED TO THE APPROPRIATE TAG TAG DEFICIENCY) R 000 Initial Comments R 000 The facility was found to be in substantial compliance with the fire and life safety requirements of the Rules for Residential or Assisted Living Facilities in Idaho. No core deficiencies were cited during the standard fire/life safety survey conducted on February 21, 2007. The surveyor conducting the survey was: **Taylor Barkley** Health Facility Surveyor Facility Fire safety & Construction Bureau of Facility Standards

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

STATE FORM 6899 40S821 If continuation sheet 1 of 1

TITLE



BUREAU OF FACILITY STANDARDS P.O. Box 83720 Boise, ID 83720-0036 (208) 334-6626 fax: (208) 364-1888

ASSISTED LIVING Non-Core Issues Punch List

Facility Name	Physical Address	Phone Number
Spring Creck MANOR	653 N EAGLE Rd.	(208) 938-5578
Administrator	City	ZIP Code
Victoriana Andonesui- Ireland	EAGLE Id	83616
Survey Team Leader	Survey Type	Survey Date
TAYLOR BARKIEY		2.21-7

TA	ylor	BA	irkley	3.91-	7		
NON-CORE ISSUES							
ITEM #	COM SWADS BY	LE# 3.22	DESCRIPTION	886 20 5 5 7 7 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8	DATE RESOLVED	BFS USE	
	405	5,05	The Laundry room has a door stop installed and	is			
i sef.			holding the door open.				
š							
2.			The Laundry room has an alcohol based hand rub di	5PCNSCK			
			in stalled above the light switch.	,			
					***************************************	3 (3) (3)	
3.			The Wellness Center has an alcohol based hand ruk)			
			dispenser installed above the Light Switch.				
14.		***************************************	Resident Room # 28 is missing escutcheon plate.				
5,			Resident Room # 28 is missing escutcheon plate. Resident Room # 24 has A one inch by two inch hole	Bround			
	}		the escutcheen plate.				
6.			the escutcher plate. Resident Room # 23 is missing the escutcher plate	in closet.			
<u>-7.</u>			The bathroom closet in the bathroom by room \$20 is miss	inc		5.63 51 5	
			the escutcheon plate.				
රි.			Resident room #1 closet/is missing the escutchern signature of Facility Representative	plate.			
· ·	se Require				Date Signed		
3	16.	-7	Victoriana Irelan				



BUREAU OF FACILITY STANDARDS P.O. Box 83720 Boise, ID 83720-0036 (208) 334-6626 fax: (208) 364-1888

ASSISTED LIVING Non-Core Issues Punch List

Facility Name	Physical Address	Phone Number
Spring Creek Manor	653 N EAGLE Rd.	(208) 938-5578
Administrator	City	ZIP Code
Victoriana Andonesui- Ireland	EAGLE Id	83616
Survey Team Leader	Survey Type	Survey Date
TAYLOR BArkley		2.21.7

TA	4-1/02 B,	or Kley	2-21-7				
NON-	NON-CORE ISSUES						
ITEM #	RULE# 16.03.22	DESCRIPTION SECURITIES SECURIOR SECURI		DATE BFS RESOLVED USE			
9	405,05	Resident room # 16 is missing escutcheon plates	in				
		both closets.					
10.		The corridor has a one half inch hole in ceiling around	the				
		Resident room #7 has one half inch hole ground escut					
,			Chron				
		plate in the closet.	***************************************				
19.		The Living room has two slipped down escutcheon pi	htes,				
	<u> </u>	And mother with a one half inch hole around the	plate.				
13		The mechanical room has four pipe penetrat	ION				
		that are not sealed. One of these is a four inc	h hole.	36 26 30 20 26 30 26 30 26 30 26 30 26 30 26 30 26 30 26 30 26 30 26 30 20 26 30 20 20 20 20 20 20 20 20 20 20 20 20 20			
14,		The emercency light in Living room does not wor	-K.				
15.	415,05	The last annual sprinkler in spection was February.	twa,2006.				
16.	410.02		n: 47				
		each ourter.					
				(加克斯曼拉雷· 克克 李·马斯奇拉奇·			
	se Required Date	Signature of Facility Representative		Date Signed			
ه - کــ	ar 7	Materia Meleni	Х				